
# BUNKER

# Installing 61" / 72" Workbenches




Part No. **B300-WB61W** Stock No. **28089** 61" Workbench with Hardwood Worktop



Part No. **B300-WB61SSPP** Stock No. **28097** 61" Workbench with Stainless Steel Worktop and Power Pegboard



Part No. **B300-WB72WPP** Stock No. **28098** 72" Workbench with Hardwood Worktop and Power Pegboard




Part No. **B300-WB61SS** Stock No. **28090** 61" Workbench with Stainless Steel Worktop



Part No. **B300-WB72W** Stock No. **28091** 72" Workbench with Hardwood Worktop



Part No. **B300-WB61WPP** Stock No. **28096** 61" Workbench with Hardwood Worktop and Power Pegboard



Part No. **B300-WB72SS** Stock No. **28095** 72" Workbench with Stainless Steel Worktop



Part No. **B300-WB72SSPP** Stock No. **28099** 72" Workbench with Stainless Steel Worktop and Power Pegboard

Unpack your workbench and check to make sure that it was not damaged during transit and that all items are included.

# **WARNING!** The workbench is heavy. We recommend that 2 people unpack and assemble the workbench.

# SPECIFICATIONS

Part No.	B300-WB61W	B300-WB61WPP	B300-WB72W	B300-WB72WPP
	B300-WB61SS	B300-WB61SSPP	B300-WB72SS	B300-WB72SSPP
Dimensions	1,550 x 610 x 760 mm	1,550 x 610 x 1,267 mm	1,830 x 610 x 760 mm	1,830 x 610 x 1267 mm

#### drapertools.com

Draper Tools Limited, Hursley Road, Chandler's Ford, Eastleigh, Hampshire. SO53 1YF UK. Delta International, Delta International BV, Oude Graaf 8, 6002 NL, Weert, Netherlands

# **PARTS BREAKDOWN**

#### B300-WB61W

Ref	Description	Qty
A1	Rubber Wood Top	1
В	Left Leg	1
С	Right Leg	1
D1	Front Crossbar with BUNKER Badge	1
E1	Rear Crossbar	1
F1	Back Rail	1
G	M6 x 12mm Screws	36

#### B300-WB61WPP

Ref	Description	Qty
A1	Rubber Wood Top	1
В	Left Leg	1
С	Right Leg	1
D1	Front Crossbar with BUNKER Badge	1
E1	Rear Crossbar	1
F1	Back Rail	1
G	M6 x 12mm Screws	56
Н	Power Strip	1
I	Power Strip Holder	1
J1	Pegboard	1
К	Pegboard Left Bracket	1
L	Pegboard Right Bracket	1

#### B300-WB72W

Ref	Description	Qty
A2	Rubber Wood Top	1
В	Left Leg	1
С	Right Leg	1
D2	Front Crossbar with BUNKER Badge	1
E2	Rear Crossbar	1
F2	Back Rail	1
G	M6 x 12mm Screws	38

# B300-WB61SS

Ref	Description	Qty
AA1	Stainless Steel Top	1
В	Left Leg	1
С	Right Leg	1
D1	Front Crossbar with BUNKER Badge	1
E1	Rear Crossbar	1
F1	Back Rail	1
G	M6 x 12mm Screws	36

#### B300-WB61SSP

Ref	Description	Qty
AA1	Stainless Steel Top	1
В	Left Leg	1
С	Right Leg	1
D1	Front Crossbar with BUNKER Badge	1
E1	Rear Crossbar	1
F1	Back Rail	1
G	M6 x 12mm Screws	56
Н	Power Strip	1
I	Power Strip Holder	1
J1	Pegboard	1
К	Pegboard Left Bracket	1
L	Pegboard Right Bracket	1

#### B300-WB72SS

Ref	Description	Qty
AA2	Stainless Steel Top	1
В	Left Leg	1
С	Right Leg	1
D2	Front Crossbar with BUNKER Badge	1
E2	Rear Crossbar	1
F2	Back Rail	1
G	M6 x 12mm Screws	38

#### drapertools.com





#### B300-WB72WPP

Ref	Description	Qty
A2	Rubber Wood Top	1
В	Left Leg	1
С	Right Leg	1
D2	Front Crossbar with BUNKER Badge	1
E2	Rear Crossbar	1
F2	Back Rail	1
G	M6 x 12mm Screws	59
Н	Power Strip	1
I	Power Strip Holder	1
J2	Pegboard	1
К	Pegboard Left Bracket	1
L	Pegboard Right Bracket	1


#### B300-WB72SSPP

Ref	Description	Qty
AA2	Stainless Steel Top	1
В	Left Leg	1
С	Right Leg	1
D2	Front Crossbar with BUNKER Badge	1
E2	Rear Crossbar	1
F2	Back Rail	1
G	M6 x 12mm Screws	59
Н	Power Strip	1
I	Power Strip Holder	1
J2	Pegboard	1
K	Pegboard Left Bracket	1
L	Pegboard Right Bracket	1

# ASSEMBLY

### 1. Left and Right Legs (B & C)

- Place the worktop topside down onto a protective piece of cardboard.
- Attach the left and right legs to the underside of the worktop.
- Align the pre-drilled holes in worktop with holes on top of legs.
- Partially tighten M6 x 12mm screws (G) through each leg into worktop.



BUNCER

#### drapertools.com


Draper Tools Limited, Hursley Road, Chandler's Ford, Eastleigh, Hampshire. SO53 1YF UK. Delta International, Delta International BV, Oude Graaf 8, 6002 NL, Weert, Netherlands

## 2. Front and Rear Crossbars (D1 & E1 & D2 & E2)

- Attach crossbars to the front and back of left and right legs.
- Align the pre-drilled holes in worktop with holes in crossbars.
- Partially tighten M6 x 12mm screws (G) through each crossbar into worktop.
- Align crossbars end holes with holes in left and right legs.
- On each end of crossbars, partially tighten M6 x 12mm screws (G) through

crossbar holes into leg holes.

Note: The crossbars end flanges must be attached so that they are on the outside of the legs.




## 3. Back Rail (F1 & F2)

- Attach back rail to back of left and right legs.
- Align back rail end holes with holes in back of left and right legs.
- Tighten M6 x 12mm screws (G) through back rail end holes into leg holes.

Note: The back rail end flanges must be attached so that they are on the outside of the legs.

• Once the back rail is attached, go back and fully tighten all screws that were

partially tightened. Take care not to over tighten the screws.




#### drapertools.com

Draper Tools Limited, Hursley Road, Chandler's Ford, Eastleigh, Hampshire. SO53 1YF UK. Delta International, Delta International BV, Oude Graaf 8, 6002 NL, Weert, Netherlands


## 4. Pegboard (J1 & J2) and Pegboard Left & Right Bracket (K & L)

- With the help of another person, carefully place the pegboard into the upright position.
- Position the pegboard left bracket over the holes on the pegboard and the leg.
- Attach the pegboard left bracket with M6 x 12mm screws (G).
- Repeat this process for the other side of the pegboard to attach it to the leg.



## 5. Power Strip (H) and Power Strip Holder (I)

- Insert the power strip into the power strip holder.
- Align the power strip holder holes with the holes in pegboard.
- Tighten M6 x 12mm screws (G) through pegboard holes into power strip holder holes.



#### drapertools.com

Draper Tools Limited, Hursley Road, Chandler's Ford, Eastleigh, Hampshire. S053 1YF UK. Delta International, Delta International BV, Oude Graaf 8, 6002 NL, Weert, Netherlands

