






• INSTRUCTIONS •

IMPORTANT: PLEASE READ THESE INSTRUCTIONS CAREFULLY TO ENSURE THE SAFE AND EFFECTIVE USE OF THIS KIT.

<p>1 IMPORTANT: Oil here before use.</p>		<p>4 Gently squeeze the handles together and the cable is held by external jaws, as the insulation is lightly cut without damaging the conductors. For cables with a hard, or soft sheath, change the blade pressure by turning the adjusting knob [D].</p>	
<p>2 To cut cable, place cable between cutter blades [A] and fully close handles.</p>		<p>5 To cut larger diameter cable, turn the adjusting knob [D] clockwise. To cut smaller diameter cable, turn anticlockwise.</p>	
<p>3 To strip cable, clamp cable between front blades [B]. Use the metric or imperial graduations marked on the lower jaws [C] to control the length to be stripped.</p>		<p>6 As the handles are closed, the sliding action of the blades removes the insulation up to 14mm in length.</p>	